1. Approving National Aviation 3. Form Tracking Number: Authority/Country: **AUTHORIZED RELEASE CERTIFICATE** RTS130335 **FAA/UNITED STATES** FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG 4. Organization Name and Address: 5. Work Order/Contract/Invoice Number: Avionica, Inc. 9941 West Jessamine Street, Miami, FL. 33157, Parts Manufacturer Approval #PQ1734CE Order#0113733/ RMA#4596/Avionica Sales Order ID:SO15557 6. Item: 7. **Description:** Part Number: Eligibility:\* 10. Quantity: Serial/Batch Number: 12. Status/Work: 1. miniQAR MKIII, Mod BCD 804-1205-03 N/A 1ea. 20251 **SEE BLOCK 13** 13. Remarks: -RETURN TO SERVICE- REBUILT (ALTERED) TO ORIGINAL PAH's SPECIFICATIONS This miniQAR MKIII has been disassembled, cleaned, inspected, repaired as necessary, reassembled and tested using new parts that conform to current approved data in accordance with miniQAR MKIII Master Drawing List 8041200MD, Rev H, dated 4/15/2013, per CFR 14 Part 43.3(j). This article is being returned to service in accordance with CFR 14 Part 43.7(d). This article is a miniQAR MKIII P/N 804-1205-03 with MFG S/N 20251. Eligibility: FAA Approved Model List (AML) 21149-AML, Rev M, dated July 18, 2013, or later FAA approved revision. \*\*\*PLEASE BE ADVISED THAT IN ALL CASES IT IS THE RESPONSIBILITY OF THE USER INSTALLER TO DETERMINE ELIGIBILITY\*\*\* The subparts and components that were replaced during the rebuild procedure are listed below: Label, PMA, Generic miniQAR, AV P/N 240-0131, Lot#: L9178 Screw, 0-80 Phil, Pan Head, 3/16, AV P/N 250-0262, Lot#: L12754 Machine Screw, #3-48 x 1/4", pan Phillips Drive Steel, AV P/N 250-0552, Lot#: L12918 miniQAR MKIII Operational Firmware Image 700-1200-01AB-ESM0060AG-700-1200-11AK (per Service Bulletin SB059 ECO1049) miniQAR MKIII Service Pack 2, 704-0230SP2 (per Service Bulletin SB070 ECO1376) 14. Certifies the items identified above were manufactured in conformity to: ☐ 14 CFR 43.9 Return to Service Other regulation specified in Block 13 Approved design data and are in a condition for safe operation. Certifies that unless otherwise specified in block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14. Code of Non-approved design data specified in Block 13. Federal Regulations, part 43 and in respect to that work, the items are approved for return to service. 15. Authorized Signature: 16. Approval/Authorization No.: 20. Authorized Signature: 21. Approval/Certificate No.: PO1734CE 17. Name (Typed of Printed): 18. Date (m/d/v): 22. Name (Typed or Printed): 23. Date (m/d/y): fames A. Morra NOV/18/2013 User/Installer Responsibilities It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block1. Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the

national regulations by the user/installer before the aircraft may be flown.



## 9941 W. Jessamine Street, Miami FL 33157 Main: 786-5441100, Fax: 786-544-1110

# **Teardown Report**

Receive Date: 10/07/13	Customer: W	orld Airways		RMA#:	4596
Quote Date: 10/07/13	Customer Ref. #: 01	13733		RW #	7659
Approval Date: 10/09/13	WARR:	Yes	✓ No	SO #:	15557
Part Number	Serial Number	Des	cription		
804-1205-03	20251		Mini QAR MK	III ( MOD BO	CD)
Customer Failure Report/Incomi	na Disposition				
Customer request to recertify unit. Ple		eded.			
			•	* * * * * * * * * * * * * * * * * * * *	
Test and Inspection Findings:		400.450			· 南阳 · 林山
SD card (GSU) in the unit is unlocked					
Unit has old configuration version (AB	3) and no SP installed.				
SD card hasFAT16 format					
AT performed and the unit passed.					
No other issues found during the rebu	ilding process.				
Both memory cards FAT32 formatted					
Tests and Procedures Performed					Carry.
Burn-in and Data validation performed					
Final Test and AT performed and the	unit passed.				
		AND AND STORY			NAMES OF THE PARTY
Notes:		ALC: THE PARTY			
QU14230					
					^
8130-3: 🗸 Yes No		EASA:	Yes ✓ No	0	
	Performed By: JA	ΛP			
	Date: 11/				*-



# **Certificate of Conformance**

Date:

November 18, 2013

Manufacturer:

Avionica, Inc.

Address of Manufacturer:

9941 West Jessamine Street.

Miami, FL. 33157

USA

Equipment Description:

miniQAR MK III, 573/429, ARINC 717, 2GB

Part Number:

804-1205-03, Mod BCD

Serial Number:

20251

Applicable Documents:

This article was manufactured in accordance with Avionica, Inc. Master Drawing List 8041200MD, Rev H, dated 4/15/2013,

(ECO1389).

Declaration:

I declare, as an authorized Avionica, Inc representative, that the above information in relation to supply/manufacture of this

product is in conformity with the stated standards and other

related documents stated above.

Jim Morra

Quality Assurance

avionica, inc.

9941 West Jessamine Street, Miami, Fl 33157, USA Voice: (786) 544-1100 Fax: (786) 544-1110

**E-mail:** <u>sales@avionica.com</u>
Web Site: <u>http://www.avionica.com</u>



RO0113733

# **REPAIR ORDER**

REPRINT

Repair Order Number Must Appear on all Shipments and Documents

## THIS IS AN ORIGINAL ORDER

Repair ltem 804-1205-03 MODBCD Item Description MINI QAR MKIII

Repair Serial 20251

Overlength PN Repair Qty

GRN 0000566678

Expected Date RO Date Priority Terms

Freight Terms

11/06/13 10/02/13 9 HEAVY MAINTENANCE NET 30 DAYS

RO Total 1 line Ext Amount USD 850.00 Currency US Dollar Container **RMA** 4596

VENDOR 72976

Address

AVIONICA INC 9941 W JESSAMINE ST MIAMI FL 33157

**UNITED STATES** 

Contact repairs Phone 786-544-1197 Fax 786-544-1110 Contact

**BILL TO** 

Address | WORLD AIRWAYS, INC HLH BUILDING 101 WORLD DRIVE ATTN: ACCOUNTS PAYABLE

PEACHTREE CITY GA 30269 **UNITED STATES** 

770-632-8000 accountspayable@woa.com

**RO ADMINISTRATOR** 

SHIP TO

Address GLOBAL SHARED SERVICES 4500 WEST TAMPA BAY BLVD. TAMPA FL 33614 UNITED STATES

Attn MIKE DUNSON Phone 813-440-5610 /6525 E-mail matcntrl@woa.com

**CLAIM ADMINISTRATOR** 

USAGE INFORMATION

BUYER

Contact Pam Gray Phone 770-632-8000 Fax 770-632-8050 Email pgray@woa.com

Contact Phone Fax

Attn

Phone

E-mail

Contact E-mail Claim #

Warrantor

REPAIR DETAIL

TPA1 Shop ATL1 Incident SIR no **PFR** no Reliability Grp

REMOVAL INFORMATION

Removed From Failure Code Date of Removal Component Time Mechanic/Cert Removal Reason 14 Trouble Shooting

N271WA 09 FAILED OPS TEST 08/22/12 14:57:00

Units Flight Hours TSI 887:16 TSN 983:19 TSO 983:19 **TSFR** 983-19

TSSV 983:19

NOTES

Comments

N271 @ TPA1

Failure Code: FAILED OPS TEST; Removal Reason: Trouble Shooting;; Old Status Operational, New Status Non-Operational. Old Loc WR16A03, New Loc USCAGE.

Shipping Instructions FEDEX

Removal Comments

LOG PAGE 497590



### RO0113733

## REPAIR ORDER

REPRINT

Repair Order Number Must Appear on all Shipments and Documents

#### WORK REQUIREMENT LIST

	Work Requirement	Quantity	Unit Cost	Cost Type	Ext Amount
1	Repairs - Repairs - equipment	1.00	850.00	TBD	850.00
	OEM - REPAIR UNIT PER OEM SPECS				

Purchasing Agent Pam Gray

Order Total

850.00

QUOTE REQUIRED- QUOTE HAS TO BE APPROVED BEFORE ANY WORK COMMENCES.
ALL REPAIR SHOPS MUST COMPLETE THIS SECTION AND RETURN WITH PART AND A COMPLETE SHOP TEAR DOWN.

\*ALL REPAIR AND OVERHAUL SERVICES MUST BE IAW ALL APPLICABLE FAA REQUIREMENTS AND OEM COMPONENT MANUAL TECHNICAL DATA UNLESS OTHERWISE SPECIFIED BY WORLD AIRWAYS.\*

#### REPAIR TEST EVALUATION:

1A\_\_\_NO TROUBLE FOUND (NTF)
2A\_\_ REMOVAL CAUSE CONFIRMED
3A\_\_ NOT RELATED TO REMOVAL CAUSE
4A\_\_ SERVICE BULLETIN INCORPORATION
5A\_\_ ENGINEERING MODIFICATION

6A COMPONENT EXCHANGE 7A BEYOND ECONOMICAL REPAIR

#### MALFUNCTION REPORT:

C\_\_\_REASON FOR REMOVAL CONFIRMED BY REPAIR AGENCY.

U\_\_\_STATED REASON FOR REMOVAL AND RETURN NOT CONFIRMED BY REPAIR AGENCY.



June 19, 2014

AERO COMPONENTS LLC PO BOX 20283 MESA, AZ 85277

Subject: Material Certification

Let this letter serve as reference to the lot of Rotable, Expendable, Standard, and Consumable aircraft and engine material, (see the attached shipping document WRLD-TPA), that was sold to AERO COMPONENTS LLC. To the best of our knowledge, all the parts are in New, Overhauled, Serviceable, or Used condition and were originally manufactured and purchased directly from a manufacturer, aftermarket distributor, or airline. To the best of our knowledge, all parts have not been subjected to severe stress or heat (i.e. as in a Major Engine Failure, Incident, or Fire).

Sincerely,

Dermont Miles,

Manager of Materials

SS/rn

**Dermont Miles** 

Title: <u>DIRECTOR OF MAINTENANCE</u>

Date: 6/23/2014



Itom	Description	Carial	0	A Cl	CONE
Item	Description	Serial		Acc Class	
804-1205-03	MINI QAR (MOD STATUS B OR C)	20207	1	11ROT	REPAIRED
804-1205-03	MINI QAR (MOD STATUS B OR C)	20249	1	11ROT	OVH
804-1205-03	MINI QAR (MOD STATUS B OR C)	20251	1	11ROT	REPAIRED
804-1205-03 MODBCD	MINI QAR MKIII	20245	1	11ROT	REPAIRED
80464-10	CARGO LOCK		1	11RCV	NEW
80466-10	PAWL		23	11EXP	NEW
80469-12	TORSION SPRING		17	11EXP	NEW
80470-12	SPRING		14	11EXP	NEW
80471-13	SHAFT for CARGO LOCK		20	11EXP	NEW
805029-01	OXY GEN SAFETY CAP		727	11EXP	NEW
8050917-0006WE	PRINTER PAPER		32	11EXP	NEW
80583-30	ROLLER TRAY		1	11RCV	NEW
80583-35	ROLLER TRAY		1	11RCV	NEW
80583-37	ROLLER TRAY		4	11EXP	NEW
80596-10	SPRING		1	11EXP	NEW
80627-10	RESTRAINT		1	11EXP	NEW
80801-20	FRAME NET		1	11RCV	NEW
80812-13	HOUSING		1	11EXP	NEW
80814-10	MOUNT BASE		11	11EXP	NEW
80814-11	MOUNT BASE HOUSING		3	11EXP	NEW
80817-10	BASE PLATE		1	11EXP	NEW
8090412	PACKING		5	11EXP	NEW
8101-21-5500	KNOB/OVEN DOOR		1	11EXP	NEW
81389-7	CONTROL RECLINE		6	11EXP	NEW
8140-1	SEAL-O RING		20	11EXP	NEW
814890-2	ACTUATOR-2.5 COMPRESS BLEED	F31982	1	11ROT	ВС
815185	KIT - S/B 73-156		4	EXP	NEW
81673-13	STUD FOR CARGO LOCK		17	11EXP	NEW
81862-10	CARGO LOCK		1	11RCV	NEW
31862-11	CARGO LOCK- DOUBLE		10	11RCV	NEW
81969-10	CARGO LOCK		1	11RCV	NEW
81974-10	CARGO LOCK		1	11RCV	NEW
81MS1-75LB	ANTI SEIZE COMPOUND		1	11EXP	NEW
822-1239-101	MANAGMENT UNIT COMM	121775	1	11ROT	REPAIRED
822-1338-003	Transponder Mode S RII RVSM	16FK1H	1	11ROT	REPAIRED
824682-407	HOSE		1	11EXP	NEW
825501-12	PUMP FUEL	4783	1	11ROT	REPAIRED
825501-12	PUMP FUEL	CSGCA10073	1	11ROT	BC
827293-407	HANDLE		1	EXP	NEW
83015-10	HOUSING		2	11EXP	NEW
			-	/11	

19. REMOVED P/N  24. LOG PAGE/PILOT REPORT 4	4. DESCRIPTION  MINICAR MKILL (MID BCD)  6. DATE  18 NOV 2013  8. REPAIR STATION W.O. #  11. REMOVED: POSITION  12. MECHANIC  20. PART REMOVED SIN	CONDITION  NEW XREPAIRED  BENCH CHECK OVERHAULED  ARKS: BEBULT (ACTERED)  ORIGINAL PAH'S  ECIFICATIONS  22. A/C TOTAL TIMES/CYCLI	14. SHELFILIFE (APPLICABLE)  15. INSPECTOR 666  3. SHOP MECHANICOC  STATION  DATE REMOVED  ES 23. POSITION  7. WOA USE ONLY