


FedEx
SERVICEABLE



Tag Number: 217503

Nomenclature: SAT , SATLINK (ARINC 429, DUAL		
Mfg. P/N ON: 804-0520-11	CPN: 2311823	
Mfg. S/N ON: 16362	T/L: 3	
CAT II/III: N	CASH: N	SL Exp Date:
Type Repair: REPAIR		
Repair details are on file under FedEx		
Repair Record No:	PO/SO: MR2335628	
Originator: SHAW, DARRELL H.	Emp No: 83054	
Chkd by Name:	Date: 12 JUL 2011	
Chkd by ID:	REPAIR STATION NO	
--- INSTALLATION DATA ---		
R and R by:	Emp no:	
A/C:	POS:	ENG/NHA:
Date:	WRI/SNRM/WO:	STA/LOC:
--- REMOVAL DATA ---		
Mfg. P/N OFF:		
Mfg. S/N OFF:		
Reason for Removal / Comments:		



MASTER COPY

August 5, 2002

Mr. John Temple
Executive Vice President
The Memphis Group
3900 Willow Lake Blvd.
Memphis, TN 38118-7040

Dear Mr. Temple,

This letter certifies that the attached list of parts came from FedEx Express inventory, contract 97-0922. In addition, to the best of my knowledge, and based on the documentation reviewed at the time of delivery, and during the part's use, or storage, none of these parts were received from a U.S. Government Military source, nor have the parts been subjected to severe stress or heat (as in a major engine failure, incident or fire).

Sincerely,

David F. Bauman
Manager Global Allocations & Provisioning
901-224-6063
dfbauman@fedex.com

Enclosure: Inventory Parts List

803996	PLATE	A2334	SV	1
804-0500	ROUTER SECURELINK	10040	SV	1
804-0500	ROUTER SECURELINK	10606	SV	1
804-0500	ROUTER SECURELINK	10714	SV	1
804-0500	ROUTER SECURELINK	10715	SV	1
804-0500	ROUTER SECURELINK	10717	SV	1
804-0500	ROUTER SECURELINK	10720	SV	1
804-0500	ROUTER SECURELINK	10721	SV	1
804-0500	ROUTER SECURELINK	10722	SV	1
804-0500	ROUTER SECURELINK	10724	SV	1
804-0500	ROUTER SECURELINK	10727	SV	1
804-0500	ROUTER SECURELINK	10728	SV	1
804-0500	ROUTER SECURELINK	10937	SV	1
804-0500	ROUTER SECURELINK	10939	SV	1
804-0500	ROUTER SECURELINK	10940	SV	1
804-0500	ROUTER SECURELINK	10948	SV	1
804-0500	ROUTER SECURELINK	11015	SV	1
804-0500	ROUTER SECURELINK	11018	SV	1
804-0500	ROUTER SECURELINK	11019	SV	1
804-0500	ROUTER SECURELINK	11021	SV	1
804-0500	ROUTER SECURELINK	11025	SV	1
804-0500	ROUTER SECURELINK	11026	SV	1
804-0500	ROUTER SECURELINK	11028	SV	1
804-0500	ROUTER SECURELINK	11097	SV	1
804-0500	ROUTER SECURELINK	11098	SV	1
804-0500	ROUTER SECURELINK	11100	SV	1
804-0500	ROUTER SECURELINK	11106	SV	1
804-0500	ROUTER SECURELINK	11111	SV	1
804-0520-11	SATLINK	15599	SV	1
804-0520-11	SATLINK	16056	SV	1
804-0520-11	SATLINK	16113	SV	1
804-0520-11	SATLINK	16120	SV	1
804-0520-11	SATLINK	16341	SV	1
804-0520-11	SATLINK	16362	SV	1
80430-10	GUIDE		SV	1
804740-409	BOX	FE826	SV	1
804740-409	BOX	FE827	SV	1
804740-409	BOX	FE828	SV	1
805367-01	NUT Y		NE	3
805431	BLADE	QMB432	AR	1
805431	BLADE		SV	5
805500-1	AIR FILTER		NE	1
80550012	FIRE EXTINGUISHER, BOTTLE	B1194	SV	1
80550012	FIRE EXTINGUISHER, BOTTLE	B1342	SV	1
80550012	FIRE EXTINGUISHER, BOTTLE	B1355	SV	1
80550012	FIRE EXTINGUISHER, BOTTLE	B1815	SV	1
80550012	FIRE EXTINGUISHER, BOTTLE	B2296	SV	1
80550012	FIRE EXTINGUISHER, BOTTLE	B2966	SV	1
80550012	FIRE EXTINGUISHER, BOTTLE	B3018	SV	1
80550012	FIRE EXTINGUISHER, BOTTLE	B311	SV	1
80550012	FIRE EXTINGUISHER, BOTTLE	B3623	SV	1
80550012	FIRE EXTINGUISHER, BOTTLE	B593	SV	1
80550012	FIRE EXTINGUISHER, BOTTLE	B650	SV	1
80550012	FIRE EXTINGUISHER, BOTTLE	B737	SV	1



GE Capital
Aviation Services

Asset Management Services

3860 East Holmes Road
Suite 108
Memphis, TN 38118
USA

July 31, 2014

AERO COMPONENTS LLC
PO BOX 20283
MESA, AZ 85277

Subject: Material Certification

This letter is in reference to the lot of Rotable aircraft material, (see the attached shipping list "GECAS-AMS July 2014"), that was sold by GECAS-AMS to AERO COMPONENTS LLC. To the best of our knowledge, all the parts are in New, Overhauled, Serviceable, or Used condition. To the best of our knowledge, all parts have not been subjected to severe stress or heat (i.e. as in a Major Engine Failure, Incident, or Fire).

Sincerely,

A handwritten signature in black ink, appearing to read 'Stan Heffington', with a horizontal line extending to the right.

Stan Heffington

GE
Capital Aviation Services
Asset Management Services
Project Manager

T 901-547-2346
E name. stan.heffington@ge.com

Stan Heffington
 GE Capital Aviation Services
 Asset Management Services
 Project Manager



GE Capital
 Aviation Services

Asset Management Services

3860 East Holmes Road
 Suite 108
 Memphis, TN 38118
 USA

775090-10-002	UNIT	86110339	AR	1	OTHER
77989-1	BELLOWS	N814FX1	AR	1	OTHER
77FW002-1	CASTER PANEL	1377116	AR	1	OTHER
77FW002-1	CASTER PANEL	1377117	AR	1	OTHER
77FW002-1	CASTER PANEL	1377118	AR	1	OTHER
77FW002-1	CASTER PANEL	1377119	AR	1	OTHER
77FW002-1	CASTER PANEL	1377120	AR	1	OTHER
77FW002-1	CASTER PANEL	1556302	AR	1	OTHER
77FW002-1	CASTER PANEL	1556303	AR	1	OTHER
77FW002-1	CASTER PANEL	1556304	AR	1	OTHER
77FW002-1	CASTER PANEL	1556305	AR	1	OTHER
77FW002-1	CASTER PANEL	1556307	AR	1	OTHER
77FW004-1	CASTER PANEL	1379084	AR	1	OTHER
77FW004-1	CASTER PANEL	1379085	AR	1	OTHER
77FW004-1	CASTER PANEL	1379087	AR	1	OTHER
77FW004-1	CASTER PANEL	1379088	AR	1	OTHER
77FW004-1	CASTER PANEL	1379089	AR	1	OTHER
77FW004-1	CASTER PANEL	1555373	AR	1	OTHER
77FW004-1	CASTER PANEL	1555374	AR	1	OTHER
77FW004-1	CASTER PANEL	1555375	AR	1	OTHER
77FW004-1	CASTER PANEL	1555376	AR	1	OTHER
77FW004-1	CASTER PANEL	1555377	AR	1	OTHER
780800-10-001	PROPULSION MULTIPLEX	EMUX5005	AR	1	OTHER
780800-10-002	PMUX EDM110-3	EMUX5082	AR	1	OTHER
7D0020D10	UNION		NE	1	OTHER
7RN	PANEL	01004	AR	1	OTHER
7RN	PANEL	0576	AR	1	OTHER
80005-11	MAT ASSY		SV	4	OTHER
802556-403JET	BOTTOM-SHEEPSKIN		SV	7	OTHER
804-0520-11	SATLINK	15599	SV	1	OTHER
804-0520-11	SATLINK	16056	SV	1	OTHER
804-0520-11	SATLINK	16113	SV	1	OTHER
804-0520-11	SATLINK	16120	SV	1	OTHER
804-0520-11	SATLINK	16341	SV	1	OTHER
804-0520-11	SATLINK	16362	SV	1	OTHER
805500-1	AIR FILTER		NE	1	OTHER
810567-01	TUBE	NSN	NE	1	OTHER
824002-401	CUSHION		SV	10	OTHER
83016-20	ROLLER	2080	AR	1	OTHER
8550-20	SMOKE DETECTOR	10078	AR	1	OTHER
8550-20	SMOKE DETECTOR	10079	AR	1	OTHER
8550-20	SMOKE DETECTOR	10080	AR	1	OTHER
8550-20	SMOKE DETECTOR	10081	AR	1	OTHER